


Start the PassThruD application. Click on Start → All Programs → PassThruD → PassThruD Configuration. Then choose PC Retriever then click on Set Default then click Apply.



Next click on the Details tab and check the 115200 Baudrate Support box. Click Apply then OK.

